

# FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

<b>UNIT</b>	UNIT TYPE:													
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Camden		
Closed MSWLF	]	HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: SLAS-15-02		
CDLF		re T&P / ollection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE		

**Date of Site Inspection: 7-23-12** 

#### **FACILITY NAME AND ADDRESS:**

Albemarle Septic Services 134 Belcross Rd Camden, NC 27921

**GPS COORDINATES**: N: 36.3711° W:-76.1732°

#### **FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Joseph Russell Telephone: 252-202-9969

Email address:

Fax:

#### **FACILITY CONTACT ADDRESS:**

Same

# **PARTICIPANTS**:

Will Burke, Environmental Senior Specialist

#### **STATUS OF PERMIT**:

# **PURPOSE OF SITE VISIT:**

Routine, Audit

### **OBSERVED VIOLATIONS**

1.n/a

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

#### FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

Page 2 of 2

# **ADDITIONAL COMMENTS**

- 1. Field border markers were up and easy to identify
- 2. Please work on weed control in the crop fields.
- 3. No serious odors or vectors were noted during this inspection
- 4. The access road was in good shape, THANK YOU.
- 5. Appropriate signage was up and easy to read.

Willabe

6. Applications appear to have been performed in a profession and responsible manner.

Please contact me if you have any questions or concerns regarding this inspection report.

Will Burke
Regional Representative

Phone: (910) 796-7397

Sent on: 8-20-12	Email	Hand delivery	US Mail	Certified No. [_]